N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
17130-16-0529
State Number
N7.5

EQUIPMENT INSPECTED

State Number: **N7.5**
Capacity: 2000
Landings: 4
Volts: 220

Type of Unit: Freight
Manuf: OTIS
Installed: 06/05/1975
Complied: 06/05/1975

Floor to Floor: 1 to 4
Speed: 100
Rope Size: 1/2
Entrances: 2

OWNER
MRS BLACKSTONE
C/O PAMLICO PROPERTIES
WASHINGTON, NC, 27889

OCCUPANT
THE RICH COMPANY
147 W MAIN ST
WASHINGTON, NC, 27889

INSPECTION INFORMATION

Inspection Date	Type Inspection	Certificate Status	Inspector	County
05/10/2017	Routine	Re-issued	16 - Moore	BEAUFORT

7

VIOLATIONS

8.6.4.7	Remove the water from the pit floor and take steps to prevent its re-entry.
8.6.4.19.2 (b)	Provide the annual no load test.

Items must be corrected by: 07/09/2017

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into complainace with current codes.

Violations pointed out to: Shannon Blackstone / Manager

Inspector _____

THIS IS NOT AN INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:
MRS BLACKSTONE
C/O PAMLICO PROPERTIES
WASHINGTON, NC, 27889