



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
17130-48-5126
State Number
H1512

EQUIPMENT INSPECTED

State Number: H1512	Type of Unit: Hand Lift	Floor to Floor: 1 to 2
Capacity: 750	Manuf: ACCESS	Speed: 20
Landings: 2	Installed: 08/17/2004	Rope Size:
Volts: 110	Complied: 08/17/2004	Entrances: 2
OWNER	OCCUPANT	
SHALLOTTE 1ST BAP CHURCH	SHALLOTTE 1ST BAP CHURCH	
4486 MAIN STREET	4486 MAIN STREET	
SHALLOTTE, NC, 28459	SHALLOTTE, NC, 28459	

INSPECTION INFORMATION

Inspection Date 05/10/2017	Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BRUNSWICK
-------------------------------	----------------------------	---------------------------------	--------------------------	---------------------

10

VIOLATIONS

Elevator Name: # 1

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: MGMT.

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

SHALLOTTE 1ST BAP CHURCH
4486 MAIN STREET
SHALLOTTE, NC, 28459