

Violations pointed out to: Front office

THIS IS NOT AN

INVOICE

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 17139-73-5066
State Number 1037

1

EQUIPMENT INSPECTED					
State Number: 1037		Type of Unit: Freight		Floor to Floor: B to 1	
Capacity: 3000		Manuf: WESTBROOK		Speed: 60	
Landings: 2		Installed: 02/17/1948		Rope Size: 1/2	
Volts: 220		Complied: 04/04/1991		Entrances: 2	
OWNER			OCCUPANT		
GRAHAM DYEING & FINISHING		GRAHAM DYEING & FINISHING			
110 N BROAD ST		110 N BROAD ST			
BURLINGTON, NC, 27215		BURLINGTON, NC, 27215			
		INS	SPECTION INFORMATION		
	Inspection Date 05/19/2017	Type Inspection Routine	Certificate Status Not Issued	Inspector 73 - James	County ALAMANCE
			VIOLATIONS		
8.6	Provide category 5 testing				
3.6	Provide safe access to machine room on roof				
3.6	Provide self closing self locking machine room door				
8.6	Remove water from pit				
Ite	ms must be corrected by: 07/18/2	017			
lotify	-		when the following corrections ha	ve been made in order to br	ng your equipment in

110 N BROAD ST BURLINGTON, NC, 27215

GRAHAM DYEING & FINISHING

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

Inspector ____