

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 17139-73-5491 State Number 910

1

| | | F | EQUIPMENT INSPECTED | | | |
|--|--|---|-------------------------------|------------------------|--|--|
| State Number: 910 Type of Unit: | | Type of Unit: Fre | ight | Floor to Floor: 1 to 2 | | |
| Capacity: 2300 Manuf: MONA | | | RCH Speed: 50 | | | |
| Landings: 2 Installed: 08/ | | | 947 | Rope Size: 1/2 | | |
| Volts: 220 Complied: 08 | | Complied: 08/04/ | 14/1947 Entrances: 1 | | | |
| OWNER | | | OCCUPANT | | | |
| ANGIE GRAVITTE / GRAHAM DYEING | | | GRAHAM DYEING & FINISHING INC | | | |
| PO BOX 2857 | | | 240 HAWKINS ST | | | |
| BURLINGTON, NC, 27216-2857 | | | BURLINGTON, NC, 27215 | | | |
| | | INS | SPECTION INFORMATION | | | |
| Inspection Date Type Inspection 05/19/2017 Routine | | Certificate Status Re-issued | Inspector 73 - James | County ALAMANCE | | |
| | | | VIOLATIONS | | | |
| 8.6.3.4 | Replace the g | governor rope. | | | | |
| 8.6.4.1.1 | | Clean the suspension means so they can be visually inspected. | | | | |
| 3.6.4.7 | Clean the pit and the pit equipment. | | | | | |
| 8.6.4.8 | Clean the machine room and the machine room equipment. | | | | | |
| 8.6.4.7 | Clean the hoistway and hoistway equipment. | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |

To make changes to the invoice mailing address please call: 919-733-0372

THIS IS NOT AN INVOICE

complainace with current codes. Violations pointed out to: Manager

Items must be corrected by: 07/18/2017

ANGIE GRAVITTE / GRAHAM DYEING

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into

An invoice will be mailed to: PO BOX 2857

BURLINGTON, NC, 27216-2857

Inspector ___