



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
17143-70-4785
State Number
H2856

EQUIPMENT INSPECTED

State Number: H2856	Type of Unit: Hand Lift	Floor to Floor: 1 to 2
Capacity: 750	Manuf: SAVARIA	Speed: 8
Landings: 2	Installed:	Rope Size:
Volts: 120	Complied:	Entrances: 2
OWNER	OCCUPANT	
NEW CHRISTIAN CHURCH	NEW CHRISTIAN CHURCH	
6448 NEW CENTER CHURCH ROAD	6448 NEW CENTER CHURCH ROAD	
SEAGROVE, NC, 27341	SEAGROVE, NC, 27341	

INSPECTION INFORMATION

Inspection Date 05/23/2017	Type Inspection New	Certificate Status Issued	Inspector 70 - Darnley	County RANDOLPH
-------------------------------	------------------------	------------------------------	---------------------------	--------------------

76

VIOLATIONS

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Kenneth Divens

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

NEW CHRISTIAN CHURCH
6448 NEW CENTER CHURCH ROAD
SEAGROVE, NC, 27341