



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
17164-73-0164
State Number
11639

EQUIPMENT INSPECTED

State Number: 11639	Type of Unit: Passenger	Floor to Floor: 1 to 3
Capacity: 2500	Manuf: THYSSEN KRUPP	Speed: 125
Landings: 3	Installed: 03/06/1986	Rope Size:
Volts: 200	Complied: 03/06/1986	Entrances: 1
OWNER	OCCUPANT	
CAROLINA BIOLOGICAL SUPPLY	CAROLINA BIOLOGICAL SUPP.	
ATTN ACCOUNTS PAYABLE	1308 RAINEY ST	
BURLINGTON, NC, 27216-6005	BURLINGTON, NC, 27215	

INSPECTION INFORMATION

Inspection Date 06/13/2017	Type Inspection Routine	Certificate Status Re-issued	Inspector 73 - James	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	-------------------------	--------------------

1

VIOLATIONS

2.27.1.1.1	Place the in-car Emergency Phone in working order.
2.14.7.1.2	Place the passenger cab interior lights in working order. 50 lx or 5 fc @ the cab floor.
2.2.5.1	Place the pit lights in working order. 100 lx or 10 fc @ the pit floor.
8.6	Place cartop station in working order

Items must be corrected by: 08/12/2017

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Maintenance

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

CAROLINA BIOLOGICAL SUPPLY
ATTN ACCOUNTS PAYABLE
BURLINGTON, NC, 27216-6005