



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
17164-73-1652
State Number
2553

EQUIPMENT INSPECTED

State Number: 2553	Type of Unit: Freight	Floor to Floor: 1 to 3
Capacity: 4000	Manuf: SOUTHERN	Speed: 75
Landings: 3	Installed: 05/17/1955	Rope Size: 1/2
Volts: 220	Complied: 05/17/1955	Entrances: 1
OWNER	OCCUPANT	
DUKE ENERGY	DUKE POWER CO	
PO BOX 1007 ST 30D	1205 N CHURCH ST	
CHARLOTTE, NC, 28201	BURLINGTON, NC, 27215	

INSPECTION INFORMATION

Inspection Date 06/13/2017	Type Inspection Routine	Certificate Status Re-issued	Inspector 73 - James	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	-------------------------	--------------------

1

VIOLATIONS

8.6.4.7 Remove the water from the pit floor and take steps to prevent its re-entry.

Items must be corrected by: 08/12/2017

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: mike.salmon@duke-energy.com

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

DUKE ENERGY
PO BOX 1007 ST 30D
CHARLOTTE, NC, 28201