



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
17165-73-2288
State Number
2259

EQUIPMENT INSPECTED

State Number: 2259	Type of Unit: Freight	Floor to Floor: 1 to 2
Capacity: 2500	Manuf: MONARCH	Speed: 75
Landings: 2	Installed: 01/08/1954	Rope Size:
Volts: 220	Complied: 02/15/1987	Entrances: 1
OWNER	OCCUPANT	
ST JOHNS BAPTIST CHURCH	H & J MANAGEMENT INC	
1615 OBERLIN RD	673 GILMER STREET	
RALEIGH, NC, 27608	BURLINGTON, NC, 27216	

INSPECTION INFORMATION

Inspection Date 06/14/2017	Type Inspection Routine	Certificate Status Re-issued	Inspector 73 - James	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	-------------------------	--------------------

1

VIOLATIONS

2.11.2.8	Replace the missing pull straps.
8.6.4.8	Clean the machine room and the machine room equipment.
8.6.4.7	Clean the pit and the pit equipment.
2.7.3.4.1	Provide a self closing self-locking machine room / space door.
2.7.9.1	Place the machine room or space lights in working order. 200 lx or 19 fc @ the machine room floor.
8.6.5.14.1	Provide the annual relief valve and hydraulic system pressure test.
5.1.21.1	Place the car alarm bell in working order. Minimum level of 80 dBA.
2.2.5.1	Place the freight cab interior lights in working order. 25 lx or 2.5 fc @ the cab floor.

Items must be corrected by: 08/13/2017

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Bob Jordan

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

ST JOHNS BAPTIST CHURCH
1615 OBERLIN RD
RALEIGH, NC, 27608