NCDOL NCDOL N. Department of labor

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number **17171-48-1388** State Number **23293**

			EQUIPMENT INSPECTED			
State Number: 23293 Type of Uni		: Passenger	Floor to Floor	Floor to Floor: 1 to 3		
Capacity: 2100 Manuf: OT		S Speed: 100				
Landings: 3 Installed: 0		0/12/2005 Rope Size:				
Volts: 208 Complied:		9/12/2005 Entrances: 1				
OWNER		OCCUPANT				
COMMUNITY ASSOCIATION MGMT.		VILLAS ON OSPREY RIDGE				
P.O. BOX 8126		178 CLUB HOUSE RD				
OCEAN ISLE, NC, 28469		SUNSET BEACH, NC, 28468				
			NSPECTION INFORMATION			
Inspection Date 06/20/2017		Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BRUNSWICK	
			VIOLATIONS			
.2.5.1	Place the pi	ace the pit lights in working order. 100 lx or 10 fc @ the pit floor.				
.6.1.4.2	Maintenand	Maintenance records shall be available to elevator personnel.				
2.27.1.1.1	Place the in-car Emergency Phone in working order.					

Items must be corrected by: 07/10/2017

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into complainace with current codes.

Violations pointed out to: UNAVAILABLE Inspector _____

To make changes to the invoice mailing address please call: 919-733-0372

THIS IS NOT AN INVOICE

COMMUNITY ASSOCIATION MGMT.

An invoice will be mailed to: P.O. BOX 8126

OCEAN ISLE, NC, 28469