## NCDOL NCDOL NA Department of John

## N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

## INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 17171-48-5124 State Number 23252

			EQUIPMENT INSPECTED			
State Number: 232	23252 Type of Unit:		Passenger Floor to Floor: 1 to 3		:: 1 to 3	
Capacity: 2100		Manuf: OTIS	}	Speed: 100		
Landings: 3 Installed: 09/12/			/2005 Rope Size:			
Volts: 208		Complied: 09/12/2005		Entrances: 1		
OWNER			OCCUPANT			
COMMUNITY ASSOCIATION MGMT.			VILLA ON OSPREY RIDGE			
P.O. BOX 8126			176 CLUB HOUSE RD			
OCEAN ISLE, NO	C, 28469		SUNSET BEACH, NC, 28468			
		 D	NSPECTION INFORMATION			
Inspection Date 06/20/2017		Inspection outine	Certificate Status Re-issued	Inspector 48 - Martin	County BRUNSWICK	1(
			VIOLATIONS			
8.6.1.4.2	Maintenance records shall be available to elevator personnel.					
2.27.1.1.1	Place the in-car Emergency Phone in working order.					
2.7.3.4.1	Provide a self-closing self-locking machine room / space door.					

Items must be corrected by: 07/20/2017

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into complainace with current codes.

Violations pointed out to: UNAVAILABLE Inspector \_\_\_\_\_

To make changes to the invoice mailing address please call: 919-733-0372

THIS IS NOT AN INVOICE

COMMUNITY ASSOCIATION MGMT.

An invoice will be mailed to: P.O. BOX 8126

OCEAN ISLE, NC, 28469