NCDOL NCDOL N. Department of labor

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 17171-48-5175 State Number 23495

			EQUIPMENT INSPECTED			
State Number	: 23495	Type of Unit:	Type of Unit: Passenger		Floor to Floor: 1 to 3	
Capacity: 21	00	Manuf: OTIS	Manuf: OTIS		Speed: 100	
Landings: 3		Installed: 02	Installed: 02/22/2006		Rope Size: 0	
Volts: 240		Complied: 0	Complied: 02/22/2006		Entrances: 1	
OWNER			OCCUPANT			
COMMUNITY ASSOCIATION MGMT.			VILLAS ON OSPREY RIDGE			
P.O. BOX 8	126		170 CLUB HOUSE RD.			
OCEAN ISL	E BEACH, NC, 2	28469	SUNSET BEACH, NC, 28468			
		I	NSPECTION INFORMATION			
		Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BRUNSWICK	10
			VIOLATIONS			
2.15.2.2	Clean & lubricate the car guiding means pivot points. [UNDER THE CAR]					
3.24.2.1		Add the correct amount of oil in the pumping unit reservoir.				
8.6.1.4.2	Maintenance records shall be available to elevator personnel.					
8.6.4.8	Clean the machine room and the machine room equipment.					
2.27.1.1.1	Place the in-car Emergency Phone in working order.					

Items must be corrected by: 07/20/2017

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into complainace with current codes.

Violations pointed out to: UNAVAILABLE Inspector _____

To make changes to the invoice mailing address please call: 919-733-0372

THIS IS NOT AN INVOICE

COMMUNITY ASSOCIATION MGMT.

An invoice will be mailed to: P.O. BOX 8126

OCEAN ISLE BEACH, NC, 28469