

THIS IS NOT AN

INVOICE

An invoice will be mailed to:

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 17172-48-0384 State Number 23292

		EQUIPMENT INSPECTED			
State Number: 23292 Type of Unit: Passenger Capacity: 2100 Manuf: OTIS Landings: 3 Installed: 09/12/2005 Volts: 208 Complied: 09/12/2005 OWNER		S /12/2005	Floor to Floor Speed: 100 Rope Size:	: 1 to 3	
			OCCUPANT		
COMMUNITY ASSOCIATION MGMT. P.O. BOX 8126			VILLAS ON OSPREY RIDGE 180 CLUB HOUSE RD		
OCEAN ISLE, NC, 28469			SUNSET BEACH, NC, 28468		
	Γ	NSPECTION INFORMATION			
Inspection Date 06/21/2017	Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BRUNSWICK	10
		VIOLATIONS			
	nce records shall be available to	•			
	ince records shall be available to e in-car Emergency Phone in work	•			
	in-car Emergency Phone in work	•			
2.27.1.1.1 Place the	in-car Emergency Phone in work	ing order.	have been made in order to	bring your equipment into	

P.O. BOX 8126 OCEAN ISLE, NC, 28469

COMMUNITY ASSOCIATION MGMT.