



INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
17172-73-0229
State Number
25793

EQUIPMENT INSPECTED

State Number: 25793	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 2000	Manuf: OTIS	Speed: 100
Landings: 2	Installed: 06/27/2008	Rope Size:
Volts: 480	Complied: 06/27/2008	Entrances: 1
OWNER	OCCUPANT	
SOUTHEAST CINEMAS	CAROUSEL CINEMAS @ ALAMANCE CROSSING	
11917 SAM ROPER DRIVE	1090 PIPER LANE	
CHARLOTTE, NC, 28269	BURLINGTON, NC, 27215	

INSPECTION INFORMATION

Inspection Date 06/21/2017	Type Inspection Routine	Certificate Status Re-issued	Inspector 73 - James	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	-------------------------	--------------------

1

VIOLATIONS

- 2.14.7.1.3 Place the in-car emergency lights in working order. The auxillary lighting illumination shall not be less than 2 lx (0.2 fc) measured at any point between 48 in. and 35 in. above the car floor and approximately 12 in. centered horizontally in front o
- 8.6.4.7 Clean the pit and the pit equipment.
- 8.6 Repair emergency phone button
- 8.6 Perform annual pressure test
- 8.6 Place alarm bell in working order

Items must be corrected by: 08/20/2017

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into complainance with current codes.

Violations pointed out to: carouselalamance@yahoo.com

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

SOUTHEAST CINEMAS
11917 SAM ROPER DRIVE
CHARLOTTE, NC, 28269