

THIS IS NOT AN

INVOICE

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 17172-73-0880 State Number 25484

		I	EQUIPMENT INSPECTED			
State Number: 25484 Type of Unit		Type of Unit: F	Passenger	Floor to Floor: 1	Floor to Floor: 1 to 3	
Capacity: 2500 Manuf: SCHI			DLER	Speed: 100		
Landings: 3 Installed: 03/1		/2008	Rope Size:			
Volts: 208 Complied:				Entrances: 1		
OWNER		OCCUPANT				
ETHAN POINTE APARTMENTS			ETHAN POINTE APARTMENTS			
2978 ETHAN P	OINTE DRIVE		1176 KIRKPATRICK ROAD			
BURLINGTON, NC, 27215			BURLINGTON, NC, 27215			
		IN:	SPECTION INFORMATION			
Inspection Date 06/21/2017		Type Inspection Routine	Certificate Status Re-issued	Inspector 73 - James	County ALAMANCE	
			VIOLATIONS			
2.27.1.1.1	Place the in-car Emergency Phone in working order.					
8.6.1.6.5	Provide a class ABC fire extinguisher in the machinery space.					
8.6.5.14.1	Provide the annual relief valve and hydraulic system pressure test.					
8.6		Take steps to remove bump between 1st and 2nd landing				
		/20/2017				
Items must be	e corrected by: 08/	/20/201/				
	or Bureau in writii		when the following corrections hav	re been made in order to bri	ng your equipment into	

ETHAN POINTE APARTMENTS

2978 ETHAN POINTE DRIVE

BURLINGTON, NC, 27215

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to: