



N C Department of Labor Elevator Bureau  
1101 Mail Service Center, Raleigh, NC 27699-1101

### INSPECTION REPORT

IMPORTANT: Always use State Number in  
any correspondence relating to your equipment  
[www.nclabor.com/elevator.htm](http://www.nclabor.com/elevator.htm)  
919-707-7927

Report Number  
**17172-73-3531**  
State Number  
**25342**

#### EQUIPMENT INSPECTED

State Number: <b>25342</b>	Type of Unit: Passenger	Floor to Floor: 1 to 3
Capacity: 2500	Manuf: SCHINDLER	Speed: 100
Landings: 3	Installed: 10/24/2007	Rope Size:
Volts: 208	Complied:	Entrances: 1
OWNER	OCCUPANT	
ETHAN POINTE APARTMENTS	ETHAN POINTE APARTMENTS	
2978 ETHAN POINTE DRIVE	1176 KIRKPATRICK ROAD	
BURLINGTON, NC, 27215	BURLINGTON, NC, 27215	

#### INSPECTION INFORMATION

Inspection Date 06/21/2017	Type Inspection Routine	Certificate Status Re-issued	Inspector 73 - James	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	-------------------------	--------------------

1

#### VIOLATIONS

8.6.4.7	Clean the pit and the pit equipment.
8.6.4.7	Remove the water from the pit floor and take steps to prevent its re-entry.
2.27.1.1.1	Place the in-car Emergency Phone in working order.
8.6.1.6.5	Provide a class ABC fire extinguisher in the machinery space.

Items must be corrected by: 08/20/2017

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: [kbacon@bluestone-prop.com](mailto:kbacon@bluestone-prop.com)

Inspector \_\_\_\_\_

THIS IS NOT AN  
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

ETHAN POINTE APARTMENTS  
2978 ETHAN POINTE DRIVE  
BURLINGTON, NC, 27215