



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
17173-73-3529
State Number
31096

EQUIPMENT INSPECTED

State Number: 31096	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 4500	Manuf: OTIS	Speed: 100
Landings: 2	Installed:	Rope Size:
Volts: 208	Complied:	Entrances: 1
OWNER	OCCUPANT	
THE LAMBS CHAPEL	THE LAMBS CHAPEL AIRPORT CAMPUS	
415 ROXBORO ROAD	ALAMANCE ROAD	
HAW RIVER, NC, 27258	BURLINGTON, NC, 27215	

INSPECTION INFORMATION

Inspection Date 06/22/2017	Type Inspection New	Certificate Status Not Issued	Inspector 73 - James	County ALAMANCE
-------------------------------	------------------------	----------------------------------	-------------------------	--------------------

1

VIOLATIONS

- 8.6 Patch all holes in hoistway
- 8.6 Place smoke detector / heat detector 48 inches from pit floor
- 8.6 Place smoke head in pit at 24 inches from pit floor
- 8.6 Remove any piping from behind pit ladder
- 8.6 Make sump pump grate removable
- 8.6 Provide no-slip tape on pit ladder rungs

Items must be corrected by: 08/21/2017

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: OTIS

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

THE LAMBS CHAPEL
415 ROXBORO ROAD
HAW RIVER, NC, 27258