



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
17177-73-0956
State Number
20130

EQUIPMENT INSPECTED

State Number: 20130	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 2100	Manuf: MINNESOTA	Speed: 100
Landings: 2	Installed: 07/10/2001	Rope Size:
Volts: 480	Complied: 08/08/2001	Entrances: 2
OWNER	OCCUPANT	
ALAMANCE BURLINGTON SCH SYS	WOODLAWN MIDDLE SCHOOL	
1712 VAUGHN RD	3970 MEBANE ROGERS RD	
BURLINGTON, NC, 27215	MEBANE, NC, 27302	

INSPECTION INFORMATION

Inspection Date 06/26/2017	Type Inspection Routine	Certificate Status Re-issued	Inspector 73 - James	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	-------------------------	--------------------

VIOLATIONS

2.14.7.1.2	Place the passenger cab interior lights in working order. 50 lx or 5 fc @ the cab floor.
8.6.5.14.1	Provide the annual relief valve and hydraulic system pressure test.
2.27.1.1.1	Place the in-car Emergency Phone in working order.

Items must be corrected by: 08/25/2017

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: sarah_wrightenberry@abss.k12.nc.us

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

ALAMANCE BURLINGTON SCH SYS
1712 VAUGHN RD
BURLINGTON, NC, 27215