



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
17177-73-568
State Number
5904

EQUIPMENT INSPECTED

| | | |
|---------------------------|-----------------------|------------------------|
| State Number: 5904 | Type of Unit: Freight | Floor to Floor: 1 to 2 |
| Capacity: 3000 | Manuf: WESTBROOK | Speed: 35 |
| Landings: 2 | Installed: 08/09/1967 | Rope Size: |
| Volts: 550 | Complied: 09/19/1994 | Entrances: 1 |
| OWNER | OCCUPANT | |
| KINGSDOWN INC | KINGSDOWN INC | |
| 126 W HOLT ST | 126 W HOLT ST | |
| MEBANE, NC, 27302 | MEBANE, NC, 27302 | |

INSPECTION INFORMATION

| | | | | |
|-------------------------------|----------------------------|---------------------------------|-------------------------|--------------------|
| Inspection Date 06/26/2017 | Type Inspection Routine | Certificate Status Re-issued | Inspector 73 - James | County ALAMANCE |
|-------------------------------|----------------------------|---------------------------------|-------------------------|--------------------|

1

VIOLATIONS

| | |
|-----------|--|
| 2.7.3.4.1 | Provide a self closing self-locking machine room / space door. |
| 8.6.4.7 | Clean the pit and the pit equipment. |
| 2.2.5.1 | Place the freight cab interior lights in working order. 25 lx or 2.5 fc @ the cab floor. |

Items must be corrected by: 08/25/2017

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: rallmond@kingsdown.com

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

KINGSDOWN INC
126 W HOLT ST
MEBANE, NC, 27302