



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
17178-73-2913
State Number
13815

EQUIPMENT INSPECTED

State Number: 13815	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 2100	Manuf: THYSSEN KRUPP	Speed: 125
Landings: 2	Installed: 10/25/1990	Rope Size:
Volts: 208	Complied: 10/25/1990	Entrances: 1
OWNER	OCCUPANT	
ALAMANCE CO SCHOOLS	GRAHAM MIDDLE SCHOOL	
1712 VAUGHAN RD	311 PINE STREET	
BURLINGTON, NC, 27217	GRAHAM, NC, 27253	

INSPECTION INFORMATION

Inspection Date 06/27/2017	Type Inspection Routine	Certificate Status Re-issued	Inspector 73 - James	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	-------------------------	--------------------

1

VIOLATIONS

2.14.7.1.2	Place the passenger cab interior lights in working order. 50 lx or 5 fc @ the cab floor.
8.6.4.7	Remove the water from the pit floor and take steps to prevent its re-entry.
8.6.5.14.1	Provide the annual relief valve and hydraulic system pressure test.
8.6	Provide in case of fire sign at each landing

Items must be corrected by: 08/26/2017

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: vernetta_day@abss.k12.nc.us

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

ALAMANCE CO SCHOOLS
1712 VAUGHAN RD
BURLINGTON, NC, 27217