

## N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

## INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 17179-16-4652 State Number 12189

	E	QUIPMENT INSPECTED			
State Number: 12189 Type of Unit: Passo		senger Floor to Floor: 1 to 2			
Capacity: 2000	Manuf: KONE Installed: 01/29/1987		Speed: 100	Speed: 100 Rope Size: 0	
Landings: 2			Rope Size: 0		
Volts: 200	Complied: 02/03/1987		Entrances: 1		
OWNER	OCCUPANT				
FIRST SOUTH BANK		FIRST SOUTH BANK			
PO BOX 2047		1311 CAROLINA AVE			
WASHINGTON, NC, 27887		WASHINGTON, NC, 27889			
	INS	SPECTION INFORMATION			
Inspection Date 06/28/2017	Type Inspection Routine	Certificate Status Re-issued	Inspector 16 - Moore	County BEAUFORT	
		VIOLATIONS			
Notify the Elevator Bureau in womplainace with current codes.	rriting on Corrected Violations Form v	when the following corrections have	e been made in order to brir	ng your equipment into	
Violations pointed out to: Office			Inspector		
	To make changes to the invoice ma				
THIS IS NOT AN INVOICE	An invoice will be mailed to:	FIRST SOUTH BANK PO BOX 2047 WASHINGTON, NC, 27887			