

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-807-2770

| |
|---|
| Report Number 17186-73-3258 State Number 17516 |
|---|

EQUIPMENT INSPECTED

| | | |
|----------------------------|-------------------------|------------------------|
| State Number: 17516 | Type of Unit: Passenger | Floor to Floor: B to 2 |
| Capacity: 2500 | Manuf: OTIS | Speed: 100 |
| Landings: 3 | Installed: 07/21/1998 | Rope Size: |
| Volts: 208 | Complied: 07/21/1998 | Entrances: 1 |
| OWNER | OCCUPANT | |
| B D DIAGNOSTICS | B D DIAGNOSTICS | |
| 780 PLANTATION DR | 780 PLANTATION DR | |
| BURLINGTON, NC, 27215 | BURLINGTON, NC, 27215 | |

INSPECTION INFORMATION

| | | | | |
|-------------------------------|----------------------------|---------------------------------|-------------------------|--------------------|
| Inspection Date 07/05/2017 | Type Inspection Routine | Certificate Status Re-issued | Inspector 73 - James | County ALAMANCE |
|-------------------------------|----------------------------|---------------------------------|-------------------------|--------------------|

1

VIOLATIONS

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: devie_ingold@bd.com

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

B D DIAGNOSTICS
780 PLANTATION DR
BURLINGTON, NC, 27215