



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
17186-73-3363
State Number
20809

EQUIPMENT INSPECTED

State Number: 20809	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 2500	Manuf: THYSSEN KRUPP	Speed: 95
Landings: 2	Installed: 07/30/2002	Rope Size: 0
Volts: 208	Complied: 07/30/2002	Entrances: 1
OWNER	OCCUPANT	
ST. MARK'S CHURCH	ST. MARK'S CHURCH	
1230 ST. MARK'S CH. RD.	1230 ST. MARK'S CH. RD.	
BURLINGTON, NC, 27215	BURLINGTON, NC, 27215	

INSPECTION INFORMATION

Inspection Date 07/05/2017	Type Inspection Routine	Certificate Status Re-issued	Inspector 73 - James	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	-------------------------	--------------------

1

VIOLATIONS

- 2.27.1.1.1 Place the in-car Emergency Phone in working order. (location)
- 2.14.7.1.2 Place the passenger cab interior lights in working order. 50 lx or 5 fc @ the cab floor.
- 8.6.4.8.2 Articles or materials not necessary for the maintenance or operation of the elevator shall not be stored in machinery spaces, machine rooms, control spaces and control rooms.
- 8.6.5.14.1 Provide the annual relief valve and hydraulic system pressure test.
- 8.6 Replace missing kellum grip on elevator platform

Items must be corrected by: 09/03/2017

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: robert@exploresmc.org

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

ST. MARK'S CHURCH
1230 ST. MARK'S CH. RD.
BURLINGTON, NC, 27215