NCDOL NCDOL NA Department of John

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 17200-48-0568 State Number H2701

	E	QUIPMENT INSPECTED			
State Number: H2701 Type of Unit: Har			I Lift Floor to Floor: 1 to 2		
Capacity: 750	Manuf: GARAVENTA Installed: 10/27/2015		Speed: 10		
Landings: 2				Rope Size:	
Volts: 120 Complied: 10/27/2015		Entrances: 2			
OWNER		OCCUPANT			
BRADFORD PRDUCTS	BRADFORD PRDUCTS				
2101 ENTERPRISE DRIVE LELAND, NC, 28451 LELAND, NC, 28451 LELAND, NC, 28451					
	INS	SPECTION INFORMATION			
Inspection Date 07/19/2017	Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BRUNSWICK 10	
		VIOLATIONS			
Elevator Name: # 1					
Notify the Elevator Bureau in w complainace with current codes	vriting on Corrected Violations Form v	when the following corrections	have been made in order to	bring your equipment into	
Violations pointed out to: MGMT			Inspector		
	To make changes to the invoice ma	iling address please call: 919-7			
THIS IS NOT AN INVOICE	An invoice will be mailed to:	BRADFORD PRDUCTS 2101 ENTERPRISE DR LELAND, NC. 28451	5		