

THIS IS NOT AN

INVOICE

## N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

## INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927

Report Number 17206-73-361 State Number 8573

1

EQUIPMENT INSPECTED						
State Number: 8573		Type of Unit: Pas	Type of Unit: Passenger		Floor to Floor: 1 to 2	
Capacity: 2000		Manuf: OTIS		Speed: 100		
		Installed: 04/06/1	Installed: 04/06/1976		Rope Size:	
Volts: 460 Complied: 04/06		1976	Entrances: 1			
OWNER		•	OCCUPA	NT		
ALAMANCE-BURLINGTON SCHOOL SYSTEM				'S ELEMENTARY SCHO	OI	
1712 VAUGHN RD			2630 BUCKINGHAM RD			
BURLINGTON, NC, 27215			BURLINGTON, NC, 27215			
		INS	SPECTION INFORMATION			
Inspection Date 07/25/2017		Type Inspection Routine	Certificate Status Re-issued	Inspector 73 - James	County ALAMANCE	
			VIOLATIONS			
8.6.5.14.1 8.6 8.6	Provide the annua Tighten loose har	al relief valve and hydraulic system	order. 50 lx or 5 fc @ the cab floor.  In pressure test.			
	t be corrected by: 09/					
	vator Bureau in writing ith current codes.	ng on Corrected Violations Form v	when the following corrections have	re been made in order to br	ing your equipment into	
iolations poir	nted out to: leigh_dos	ss@abss.k12.nc.us		Inspector		

1712 VAUGHN RD BURLINGTON, NC, 27215

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

ALAMANCE-BURLINGTON SCHOOL SYSTEM