

THIS IS NOT AN INVOICE

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 17207-73-3332 State Number 23035

EQUIPMENT INSPECTED				
State Number: 23035 Type of U		assenger	Floor to Floor: 1	to 3
Capacity: 2500 Manuf: SCHI		DLER	Speed: 100	
Landings: 3 Installed: 08/		/2005	Rope Size:	
Volts: 480 Complied: 08/		6/2005	Entrances: 1	
OWNER	O	CCUPANT		
ALAMANCE COMMUNITY COLLEGE		ALAMANCE COMMUNITY COLLEGE LEARNING CENT		
1247 JIMMY KERR ROAD		1247 JIMMY KERR RD		
GRAHAM, NC, 27235		GRAHAM, NC, 27235		
	INS	PECTION INFORMATION		
Inspection Date 07/26/2017	Type Inspection Routine	Certificate Status Re-issued	Inspector 73 - James	County ALAMANCE
		VIOLATIONS		
8.6 Machine room not to	be used for storage			
Items must be corrected by: 09/24/2017		Elevator Name: G BLDG CAR 2		
lotify the Elevator Bureau in writing or omplainace with current codes.	Corrected Violations Form v	when the following corrections have	ve been made in order to br	ng your equipment into
Violations pointed out to: Maintenance		Inspector		

Page 1 of 1

ALAMANCE COMMUNITY COLLEGE 1247 JIMMY KERR ROAD GRAHAM, NC, 27235

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to: