



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
17208-73-0120
State Number
2153

EQUIPMENT INSPECTED

State Number: 2153	Type of Unit: Freight	Floor to Floor: 1 to 3
Capacity: 4000	Manuf: MONARCH	Speed: 60
Landings: 3	Installed: 07/22/1953	Rope Size:
Volts: 550	Complied: 07/22/1953	Entrances: 2
OWNER	OCCUPANT	
INTERNATIONAL TEXTILE GROUP, INC.	BURLINGTON FINISHING	
906 ANTHONY ST	906 ANTHONY ST	
BURLINGTON, NC, 27215	BURLINGTON, NC, 27215	

INSPECTION INFORMATION

Inspection Date 07/27/2017	Type Inspection Routine	Certificate Status Re-issued	Inspector 73 - James	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	-------------------------	--------------------

1

VIOLATIONS

2.11.11.5	Repair the damaged hoistway doors. Top door latch
8.6.4.7	Clean the pit and the pit equipment.
8.6.5.14.1	Provide the annual relief valve and hydraulic system pressure test.

Items must be corrected by: 09/25/2017

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: alvin.leath@burlington.com

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

INTERNATIONAL TEXTILE GROUP, INC.
906 ANTHONY ST
BURLINGTON, NC, 27215