



N C Department of Labor Elevator Bureau  
1101 Mail Service Center, Raleigh, NC 27699-1101

### INSPECTION REPORT

IMPORTANT: Always use State Number in  
any correspondence relating to your equipment  
[www.nclabor.com/elevator.htm](http://www.nclabor.com/elevator.htm)  
919-707-7927

Report Number  
**17208-73-0669**  
State Number  
**27912**

### EQUIPMENT INSPECTED

State Number: <b>27912</b>	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 2100	Manuf: TKE	Speed: 135
Landings: 2	Installed: 10/18/2011	Rope Size:
Volts: 208	Complied: 10/18/2011	Entrances: 1
OWNER	OCCUPANT	
ALAMANCE BURLINGTON SCHOOL SYSTEM	ALAMANCE CAREER & TECHNICAL CENTER	
1712 VAUGHN STREET	2550 BUCKINGHAM ROAD	
BURLINGTON, NC, 27217	BURLINGTON, NC, 27217	

### INSPECTION INFORMATION

Inspection Date 07/27/2017	Type Inspection Routine	Certificate Status Re-issued	Inspector 73 - James	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	-------------------------	--------------------

### VIOLATIONS

2.14.7.1.2	Place the passenger cab interior lights in working order. 50 lx or 5 fc @ the cab floor.
2.2.5.1	Place the pit lights in working order. 100 lx or 10 fc @ the pit floor.

Items must be corrected by: 09/25/2017

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: [lynne\\_bell@abss.k12.nc.us](mailto:lynne_bell@abss.k12.nc.us)

Inspector \_\_\_\_\_

THIS IS NOT AN  
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

ALAMANCE BURLINGTON SCHOOL SYSTEM  
1712 VAUGHN STREET  
BURLINGTON, NC, 27217