



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
17208-73-1727
State Number
1307

EQUIPMENT INSPECTED

State Number: 1307	Type of Unit: Freight	Floor to Floor: 1 to 2
Capacity: 2000	Manuf: MONARCH	Speed: 50
Landings: 2	Installed: 08/17/1949	Rope Size: 1/2
Volts: 480	Complied: 08/17/1949	Entrances: 1
OWNER	OCCUPANT	
THE TIRE CENTER OF BURLINGTON INC	THE TIRE CENTER OF BURLINGTON INC	
508 S CHURCH ST	508 S CHURCH ST	
BURLINGTON, NC, 27215	BURLINGTON, NC, 27215	

INSPECTION INFORMATION

Inspection Date 07/27/2017	Type Inspection Routine	Certificate Status Re-issued	Inspector 73 - James	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	-------------------------	--------------------

1

VIOLATIONS

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: tirecenter@bellsouth.com

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

THE TIRE CENTER OF BURLINGTON INC
508 S CHURCH ST
BURLINGTON, NC, 27215