



N C Department of Labor Elevator Bureau  
1101 Mail Service Center, Raleigh, NC 27699-1101

### INSPECTION REPORT

IMPORTANT: Always use State Number in  
any correspondence relating to your equipment  
[www.nclabor.com/elevator.htm](http://www.nclabor.com/elevator.htm)  
919-707-7927

Report Number  
**17208-73-3820**  
State Number  
**H2762**

### EQUIPMENT INSPECTED

State Number: <b>H2762</b>	Type of Unit: Hand Lift	Floor to Floor: 1 to 2
Capacity: 750	Manuf: SAVARIA	Speed: 8
Landings: 2	Installed: 09/21/2016	Rope Size:
Volts: 120	Complied:	Entrances: 2
OWNER	OCCUPANT	
LIDL US LLC	MGP DISTRIBUTION	
3500 S CLARK STREET	3815 SENATOR RALPH SCOTT PARKWAY	
ARLINGTON, VA, 22202	MEBANE, NC, 27032	

### INSPECTION INFORMATION

Inspection Date 07/27/2017	Type Inspection Routine	Certificate Status Re-issued	Inspector 73 - James	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	-------------------------	--------------------

1

### VIOLATIONS

2.27.1.1.1 Place the in-car Emergency Phone in working order.

Items must be corrected by: 09/25/2017

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: [robert.eilers@lidl.us](mailto:robert.eilers@lidl.us)

Inspector \_\_\_\_\_

THIS IS NOT AN  
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

LIDL US LLC  
3500 S CLARK STREET  
ARLINGTON, VA, 22202