

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927

Report Number 17254-76-2337 State Number 19556

5

	EQUI	PMENT INSPECTED	
State Number: 19556	Type of Unit: Passenge	Type of Unit: Passenger	
Capacity: 3500	Manuf: THYSSEN KR	LUPP	Speed: 100
Landings: 2	Installed: 12/21/2000		Rope Size:
Volts: 480	Complied: 12/21/2000		Entrances: 1
OWNER		OCCUPANT	
ASHE CO COMMISSIONI	ERS	ASHE CO AGRICULTURE OFFIC	CE CE
150 GOV'T CIRCLE STE 2	500	134 GOV'T CIRCLE	
JEFFERSON, NC, 28640		JEFFERSON, NC, 28640	
	INSPEC	TION INFORMATION	
Inspection Date 09/11/2017	Type Inspection Routine	Certificate Status Re-issued	Inspector County 76 - Crank ASHE
		VIOLATIONS	
between 48 in. an 8.6.4.8.2 Articles or materi spaces and contro 2.29.1 Assign identificat 2.29.1 Assign identificat 8.6.11.1 Provide a monthly 5.1.21.1 Place the car alarm	mergency lights in working order. The auxillad 35 in. above the car floor and approximatel als not necessary for the mainternace or operal rooms. ion numbers or letters to the equipment where ion numbers or letters to the equipment where y log on the results of the Phase I and Phase I and Phase I in bell in working order. Minimum level of 80 mergency Phone in working order.	y 12 in. centered horizontally in front ation of the elevator shall not be store e required. Provide "Do Not Use In C e required. Provide a sign for the elev I operations.	o d in machinery spaces, machine rooms, contrase Of Fire" signs at both floors
complainace with current cod Violations pointed out to: Ro	writing on Corrected Violations Form when es. dney Hopkins 336-846-5508		Inspector
THIS IS NOT AN INVOICE	To make changes to the invoice mailing An invoice will be mailed to:	address please call: 919-733-0372 ASHE CO COMMISSIONERS 150 GOV'T CIRCLE STE 2500	

JEFFERSON, NC, 28640