

THIS IS NOT AN

INVOICE

An invoice will be mailed to:

## N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

## INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 17255-70-3046 State Number 9457

		EQUIPMENT INSPECTED			
State Number: 9457	Type of Unit: Passenger		Floor to Floor: 1 to 6		
Capacity: 2000	Manuf: THYSSEN KRUPP Installed: 06/13/1980 Complied: 02/07/1997		Speed: 150 Rope Size: Entrances: 1		
Landings: 6					
Volts: 220					
OWNER		OCCUPANT			
ASHEBORO SUMMIT		ASHEBORO SUMMIT			
156 EAST ACADEMY ST		156 EAST ACADEMY ST BOX 6			
ASHEBORO, NC, 27203	ASHEBORO, NC, 27203				
		INSPECTION INFORMATION			
Inspection Date 09/12/2017	Type Inspection Routine	Certificate Status Re-issued	Inspector 70 - Darnley	County RANDOLPH	
		VIOLATIONS			
Elevator Name: #1					
	ing on Corrected Violations For	m when the following corrections h	nave been made in order to b	ring your equipment into	

ASHEBORO SUMMIT

156 EAST ACADEMY ST

ASHEBORO, NC, 27203