

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 17292-76-1351 State Number 19032

5

	EQUI	PMENT INSPECTED		
State Number: 19032 Capacity: 2500 Landings: 2	Type of Unit: Passer Manuf: SOUTHERN Installed: 05/03/200	N.	Floor to Floor: 1 to 2 Speed: 100 Rope Size:	
Volts: 208 Complied: 05/0		00	Entrances: 1	
OWNER		OCCUPANT		
LIFE STORE BANK		LIFE STORE BANK		
21 EAST ASHE ST.		21EAST ASHE ST.		
WEST JEFFERSON, NC, 28694		WEST JEFFERSON, NC, 28	8694	
	INSPEC	TION INFORMATION		
Inspection Date 10/19/2017	Type Inspection Routine	Certificate Status Re-issued	Inspector 76 - Crank	County ASHE
		VIOLATIONS		
between 48 in. and 35	in. above the car floor and approximatel	y 12 in. centered horizontally in front	0	
Items must be corrected by: 12	2/18/2017			
otify the Elevator Bureau in writi complainace with current codes.	ing on Corrected Violations Form when	the following corrections have been	made in order to bring your e	quipment into
Violations pointed out to: 336-264			Inspector	
	o make changes to the invoice mailing address please call: 919-733-0372			
THIS IS NOT AN INVOICE	An invoice will be mailed to:	LIFE STORE BANK 21 EAST ASHE ST. WEST JEFFERSON, NC, 28694		