

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 17293-76-5851 State Number 20971

5

	919-70			
	EQUIPM	MENT INSPECTED		
State Number: 20971	Type of Unit: Passenger		Floor to Floor: 1 to 2	
Capacity: 2500	Manuf: THYSSEN KRUF	PP .	Speed: 95	
andings: 2	Installed: 05/15/2002		Rope Size:	
olts: 208	Complied:		Entrances: 1	
OWNER		OCCUPANT		
LIFE STORE BANK		LIFE STORE BANK		
441 MT. JEFFERSON RD		1441 MT. JEFFERSON		
W. JEFFERSON, NC, 28694		W. JEFFERSON, NC, 286	94	
	INSPECTION	ON INFORMATION 		
Inspection Date 10/20/2017	Type Inspection Routine	Certificate Status Re-issued	Inspector 76 - Crank	County ASHE
	V)	IOLATIONS		
	ergency lights in working order. The auxillary 35 in. above the car floor and approximately 1 relief valve and hydraulic system pressure test		e less than 2 lx (0.2 fc) measure int o	ed at any point
Items must be corrected by	: 12/19/2017			
tify the Elevator Bureau in w mplainace with current codes	vriting on Corrected Violations Form when the	e following corrections have been	n made in order to bring your e	quipment into
olations pointed out to: Amy			Inspector	
THE ICNOT AN	To make changes to the invoice mailing ad-	dress please call: 919-733-0372		
THIS IS NOT AN INVOICE	An invoice will be mailed to:	IFE STORE BANK 441 MT. JEFFERSON RD V. JEFFERSON, NC, 28694		