



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
17296-76-2775
State Number
H1026

EQUIPMENT INSPECTED

State Number: H1026	Type of Unit: Hand Lift	Floor to Floor: 1 to 2
Capacity: 495	Manuf: GARAVENTA	Speed: 20
Landings: 2	Installed: 02/01/2000	Rope Size:
Volts: 220	Complied: 02/21/2000	Entrances: 2
OWNER	OCCUPANT	
ASHE CO SCHOOLS	ASHE CO MIDDLE SCHOOL	
PO BOX 604	255 NORTHWEST LANE	
JEFFERSON, NC, 28640	WARRENSVILLE, NC, 28693	

INSPECTION INFORMATION

Inspection Date 10/23/2017	Type Inspection Routine	Certificate Status Re-issued	Inspector 76 - Crank	County ASHE
-------------------------------	----------------------------	---------------------------------	-------------------------	----------------

5

VIOLATIONS

8.1 PROVIDE PROPER OPERATION OF LIFT

Items must be corrected by: 12/22/2017

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: ACMS 336-246-7175

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

ASHE CO SCHOOLS
PO BOX 604
JEFFERSON, NC, 28640