



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
17296-76-286
State Number
29345

EQUIPMENT INSPECTED

State Number: 29345	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 2500	Manuf: CANTON	Speed: 100
Landings: 2	Installed: 08/06/2014	Rope Size:
Volts: 208	Complied:	Entrances: 1
OWNER	OCCUPANT	
ST FRANCIS CATHOLIC CHURCH	ST FRANCIS CATHOLIC CHURCH	
167 ST FRANCIS PLACE	167 ST FRANCIS PLACE	
JEFFERSON, NC, 28640	JEFFERSON, NC, 28640	

INSPECTION INFORMATION

Inspection Date 10/23/2017	Type Inspection Routine	Certificate Status Re-issued	Inspector 76 - Crank	County ASHE
-------------------------------	----------------------------	---------------------------------	-------------------------	----------------

5

VIOLATIONS

8.6.4.13.1 (k)	Take steps to make the hoistway doors self-closing and self-locking.
8.6.11.1	Provide a monthly log on the results of the Phase I and Phase II operations.

Items must be corrected by: 12/22/2017

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: St. Francis Catholic Church 336-246-9151

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

ST FRANCIS CATHOLIC CHURCH
167 ST FRANCIS PLACE
JEFFERSON, NC, 28640