

## N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

## INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 17305-65-0672 State Number 24096

6

		EQUIPM	ENT INSPECTED			
State Number: 24096		Type of Unit: Passenger	Type of Unit: Passenger Floor to Floor: 1F to 1R			
Capacity: 2500		Manuf: SCHINDLER		Speed: 125		
Landings: 2		Installed: 06/19/2006		Rope Size: 0	_	
Volts: 208		Complied: 06/19/2006		Entrances: 2	Entrances: 2	
OWNER			OCCUPANT			
GRANDFATHER COUNTRY CLUB		LUB	GRANDFATHER COUNTRY CLUB			
2120 HWY.105 NORTH			1225 HWY.105 NORTH			
LINVILLE, NC, 28646			LINVILLE, NC, 28646			
		INSPECTIO	ON INFORMATION			
Inspection Date 11/01/2017		Type Inspection Routine	Certificate Status Re-issued	Inspector 65 - Kelley	County AVER	
		VI	OLATIONS			
3.6.4.7	Remove the water fr	e the water from the pit floor and take steps to prevent its re-entry.				
2.2.5.1		t lights in working order. 100 lx or 10 fc @ the pit floor.				
2.7.3.1						

\_\_\_\_\_

Elevator Name: #2

Inspector \_\_

To make changes to the invoice mailing address please call: 919-733-0372

THIS IS NOT AN INVOICE

complainace with current codes.

Items must be corrected by: 12/31/2017

Violations pointed out to: David McGuire 828-898-4531

GRANDFATHER COUNTRY CLUB
An invoice will be mailed to: 2120 HWY.105 NORTH

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into

ll be mailed to: 2120 HWY.105 NORTH LINVILLE, NC, 28646