

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 17310-48-1119 State Number 23726

EQUIPMENT INSPECTED					
				oor to Floor: 1 to 4	
Capacity: 2500 Manuf: TKE			Speed: 50		
ε					
Volts: 230 Complied: 04		/11/2006 Entrances: 1			
OWNER		OCCUPANT			
OCEAN WALK HOA					
C/O GO PROPERTY MGMT-G OWEN					
WILMINGTON, NC, 28405			OAK ISLAND, NC, 28465		
	I	NSPECTION INFORMATION			
on Date /2017	Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BRUNSWICK	10
		VIOLATIONS			
Place the su	mp pump in working order.				
Remove the water from the pit floor and take steps to prevent its re-entry.					
2.27.1.1.1 Place the in-car Emergency Phone in working order. [SAME AS LAST YR.] N/A PROVIDE PIT LIGHT SW.					
	K HOA PERTY MGMT N, NC, 28405 on Date //2017 Place the su Remove the Place the in-	Manuf: TKE Installed: 04 Complied: 04 Complied: 04 K HOA PERTY MGMT-G OWEN N, NC, 28405 On Date Type Inspection Routine Place the sump pump in working order. Remove the water from the pit floor and take s Place the in-car Emergency Phone in working	23726 Type of Unit: Passenger Manuf: TKE Installed: 04/11/2006 Complied: 04/11/2006 OC K HOA OERTY MGMT-G OWEN N, NC, 28405 OF INSPECTION INFORMATION On Date Type Inspection Re-issued VIOLATIONS Place the sump pump in working order. Remove the water from the pit floor and take steps to prevent its re-entry. Place the in-car Emergency Phone in working order. [SAME AS LAST YR.]	23726 Type of Unit: Passenger Manuf: TKE Speed: 50 Installed: 04/11/2006 Rope Size: Complied: 04/11/2006 Entrances: 1 OCCUPANT OCEAN WALK CONDO #3 PERTY MGMT-G OWEN N, NC, 28405 OAK ISLAND, NC, 28465 INSPECTION INFORMATION ODate Type Inspection Routine Type Inspection Re-issued VIOLATIONS Place the sump pump in working order. Remove the water from the pit floor and take steps to prevent its re-entry. Place the in-car Emergency Phone in working order. [SAME AS LAST YR.]	23726 Type of Unit: Passenger Floor to Floor: 1 to 4 Manuf: TKE Speed: 50 Installed: 04/11/2006 Rope Size: Complied: 04/11/2006 Entrances: 1 OCCUPANT K HOA OCEAN WALK CONDO #3 PERTY MGMT-G OWEN 105 SE 58TH STREET N, NC, 28405 OAK ISLAND, NC, 28465 INSPECTION INFORMATION ON Date Type Inspection Certificate Status Inspector County Re-issued 48 - Martin BRUNSWICK VIOLATIONS Place the sump pump in working order. Remove the water from the pit floor and take steps to prevent its re-entry. Place the in-car Emergency Phone in working order. [SAME AS LAST YR.]

To make changes to the invoice mailing address please call: 919-733-0372

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into

THIS IS NOT AN INVOICE

complainace with current codes.

Items must be corrected by: 12/06/2017

Violations pointed out to: UNAVAILABLE

An invoice will be mailed to:

OCEAN WALK HOA

C/O GO PROPERTY MGMT-G OWEN

Elevator Name: #3

Inspector ___

WILMINGTON, NC, 28405