

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 17310-48-1758 State Number 24257

			EQUIPMENT INSPECTED			
State Number: 24257 Type of Unit: Pas		assenger	Floor to Flo	Floor to Floor: 1 to 4		
Capacity: 2500 Manuf: THYSSEN KRI			EN KRUPP	P Speed: 50		
Landings: 4 Installed: 08/2		9/2006 Rop		e Size: 0		
Volts: 240 Complied:		Entrances: 1		1		
OWNER		OCCUPANT				
OCEAN WALK HOA			OCEAN WALK CONDOS #4			
C/O GO PROPERTY MGMT-G OWEN			105 SI	105 SE 58TH STREET		
WILMINGTON, NC, 28405			OAK ISLAND, NC, 28465			
		I	NSPECTION INFORMATION			
Inspection Date 11/06/2017		Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BRUNSWICK	
			VIOLATIONS			
 2.27.1.1.1	Place the in-car I	Emergency Phone in working ord	er. [SAME AS LAST YR.]			
2.2.2.4		OCEAN WALK CONDOS #4 105 SE 58TH STREET OAK ISLAND, NC, 28465 INSPECTION INFORMATION Type Inspection Certificate Status Inspector County Routine Re-issued 48 - Martin BRUNSWICK 10 VIOLATIONS mergency Phone in working order. [SAME AS LAST YR.] mp in working order.				
8.6.4.7	Remove the water	Remove the water from the pit floor and take steps to prevent its re-entry. [3 FT. OF WATER]				
8.6.4.7	Remove the water	er from the pit floor and take step	s to prevent its re-entry. [3 FT. Of	F WATER]		

Items must be corrected by: 12/06/2017 Elevator Name: #4

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into complainace with current codes.

Violations pointed out to: UNAVAILABLE Inspector _____

To make changes to the invoice mailing address please call: 919-733-0372

THIS IS NOT AN INVOICE

An invoice will be mailed to:

OCEAN WALK HOA C/O GO PROPERTY MGMT-G OWEN

WILMINGTON, NC, 28405