



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
17311-76-0054
State Number
16387

EQUIPMENT INSPECTED

State Number: 16387	Type of Unit: Passenger	Floor to Floor: 1 to 2
Capacity: 2000	Manuf: KONE	Speed: 80
Landings: 2	Installed: 11/13/1996	Rope Size:
Volts: 208	Complied: 11/26/1996	Entrances: 1

OWNER

ASHE SERVICES FOR AGING INC
180 CHATTYROB LANE
WEST JEFFERSON, NC, 28694

OCCUPANT

ASHE SERVICES FOR AGING INC
180 CHATTYROB LANE
WEST JEFFERSON, NC, 28694

INSPECTION INFORMATION

Inspection Date 11/07/2017	Type Inspection Routine	Certificate Status Re-issued	Inspector 76 - Crank	County ASHE
-------------------------------	----------------------------	---------------------------------	-------------------------	----------------

5

VIOLATIONS

- 2.7.9.1 Place the machine room or space lights in working order. Flourscent lights need to be protected
2.27.1.1.1 Place the in-car Emergency Phone in working order.

Items must be corrected by: 01/06/2018

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into complainace with current codes.

Violations pointed out to: Bill Clark 336-246-2461

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

ASHE SERVICES FOR AGING INC
180 CHATTYROB LANE
WEST JEFFERSON, NC, 28694