

THIS IS NOT AN INVOICE

## N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

## INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 17311-79-3811 State Number 23874

7

		EQUIPMENT INSPECTED			
State Number: 23874 Type of Unit: Capacity: 2500 Manuf: THY Landings: 2 Installed: 07. Volts: 208 Complied: 0		SSEN KRUPP /17/2006	Floor to Floor: 1 t Speed: 80 Rope Size: 0 Entrances: 1	o 2	
OWNER		OCCUPANT	Littanees. 1		
BAY LEAF PLANTATION	N SENIOR	BAY LEAF PL	BAY LEAF PLANTATION SENIOR		
1120 COWELL FARM RO			1120 COWELL FARM ROAD		
WASHINGTON, NC, 27889		WASHINGTON, NC, 27889			
		INSPECTION INFORMATION			
Inspection Date 11/07/2017	Type Inspection Routine	Certificate Status Re-issued	Inspector 79 - Cumberland	County BEAUFORT	
		VIOLATIONS			
8.6.1.2.1 8.6.4.13.1(i)	Provide a written maintenance Place the door restrictor in pro	1 0			
Items must be corrected by	by: 01/06/2018				
complainace with current cod	es.	orm when the following correction	is have been made in order to bring in Inspector	your equipment into	
Violations pointed out to: management office					

BAY LEAF PLANTATION SENIOR 1120 COWELL FARM ROAD WASHINGTON, NC, 27889

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to: