



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
17311-79-3869
State Number
H1969

EQUIPMENT INSPECTED

State Number: H1969	Type of Unit: Hand Lift	Floor to Floor: 1 to 2
Capacity: 750	Manuf: TKE	Speed: 12
Landings: 2	Installed: 04/23/2008	Rope Size: 0
Volts: 120	Complied: 04/23/2008	Entrances: 2
OWNER	OCCUPANT	
SECOND BAPTIST CHURCH	SECOND BAPTIST CHURCH	
2516 HWY 264 WEST	2516 HWY 264 WEST	
WASHINGTON, NC, 27889	WASHINGTON, NC, 27889	

INSPECTION INFORMATION

Inspection Date 11/07/2017	Type Inspection Routine	Certificate Status Re-issued	Inspector 79 - Cumberland	County BEAUFORT
-------------------------------	----------------------------	---------------------------------	------------------------------	--------------------

7

VIOLATIONS

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: main office

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

SECOND BAPTIST CHURCH
2516 HWY 264 WEST
WASHINGTON, NC, 27889