

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 17313-79-3687 State Number 27796

7

	I	EQUIPMENT INSPECTED			
State Number: 27796	Type of Unit: P	Passenger	Floor to Floor: 1 to	2	
Capacity: 2100	Manuf: SCHINDLER		Speed: 100		
Landings: 2	Installed: 10/25/2011		Rope Size:	Rope Size:	
Volts: 208	Complied:		Entrances: 2		
OWNER	OCCUPANT				
FIRST BAPTIST CHURCH	FIRST BAPTIST CHURCH				
113 N HARVEY STREET		113 N HARVEY STREET			
WASHINGTON, NC, 27889		WASHINGTON, N	IC, 27889		
	INS	SPECTION INFORMATION			
Inspection Date 11/09/2017	Type Inspection Routine	Certificate Status Re-issued	Inspector 79 - Cumberland	County BEAUFORT	
		VIOLATIONS			
Notify the Elevator Bureau in write omplainace with current codes.	ting on Corrected Violations Form	when the following corrections ha	ave been made in order to bring	g your equipment into	
Violations pointed out to: chruch			Inspector		
	To make changes to the invoice ma				
THIS IS NOT AN INVOICE	An invoice will be mailed to:	FIRST BAPTIST CHURC 113 N HARVEY STREET WASHINGTON, NC. 278			