

THIS IS NOT AN

INVOICE

An invoice will be mailed to:

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 17317-65-0635 State Number 9311

6

	EQU	JIPMENT INSPECTED		
State Number: 9311	Type of Unit: Passenger		Floor to Floor: 1 to 2	
Capacity: 2100	Manuf: THYSSEN KR	UPP	Speed: 125	
Landings: 2	Installed: 10/24/1979		Rope Size: 0	
Volts: 240	Complied: 10/24/1979		Entrances: 1	
OWNER		OCCUPANT		
AVERY COUNTY SCHOOLS	NEWLAND ELEMENTARY SCHOOL			
775 CRANBERRY STREET	ET 750 LINVILLE STREET			
NEWLAND, NC, 28657	1	NEWLAND, NC, 28657		
	INSPE	CTION INFORMATION		
Inspection Date 11/13/2017	Type Inspection Compliance	Certificate Status Prev Issued	Inspector 65 - Kelley	County AVERY
		VIOLATIONS		
Notify the Elevator Bureau in writing complainace with current codes.	on Corrected Violations Form when	n the following corrections have be	en made in order to bring you	· equipment into

AVERY COUNTY SCHOOLS

775 CRANBERRY STREET NEWLAND, NC, 28657