



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
17317-65-5223
State Number
H1097

EQUIPMENT INSPECTED

State Number: H1097	Type of Unit: Hand Lift	Floor to Floor: 1 to 2
Capacity: 750	Manuf: ACCESS	Speed: 15
Landings: 2	Installed: 03/29/2001	Rope Size: 0
Volts: 120	Complied: 04/04/2001	Entrances: 2
OWNER	OCCUPANT	
NEWLAND FIRST BAPTIST CHURCH	NEWLAND FIRST BAPTIST CHURCH	
PO BOX 485	160 CRANBERRY STREET	
NEWLAND, NC, 28657	NEWLAND, NC, 28657	

INSPECTION INFORMATION

Inspection Date 11/13/2017	Type Inspection Not Inspected	Certificate Status Not Issued	Inspector 65 - Kelley	County AVERY
-------------------------------	----------------------------------	----------------------------------	--------------------------	-----------------

6

VIOLATIONS

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: n/a

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

NEWLAND FIRST BAPTIST CHURCH
PO BOX 485
NEWLAND, NC, 28657