



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
17326-73-1713
State Number
H79

EQUIPMENT INSPECTED

State Number: H79	Type of Unit: Hand Lift	Floor to Floor: 1 to 2
Capacity: 500	Manuf: TOCE	Speed: 12
Landings: 2	Installed: 01/07/1982	Rope Size:
Volts: 110	Complied: 01/07/1982	Entrances: 2
OWNER	OCCUPANT	
FIRST BAPTIST CHURCH	FIRST BAPTIST CHURCH	
PO BOX 2686	400 S BROAD ST	
BURLINGTON, NC, 27216-2686	BURLINGTON, NC, 27215	

INSPECTION INFORMATION

Inspection Date 11/22/2017	Type Inspection Routine	Certificate Status Re-issued	Inspector 73 - James	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	-------------------------	--------------------

1

VIOLATIONS

8.6.4.13.1 (e) Place the hoistway door unlocking devices (interlocks) in proper working order. Bottom door

Items must be corrected by: 01/21/2018

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Danny Scott 336 214 5145

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

FIRST BAPTIST CHURCH
PO BOX 2686
BURLINGTON, NC, 27216-2686