

THIS IS NOT AN

INVOICE

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 17326-73-3714 State Number 12511

1

EQUIPMENT INSPECTED						
State Number: 12511 Capacity: 2500		Type of Unit: Passenger Manuf: MECO		Floor to Floor: 1 to 3 Speed: 150		
Landings: 3		Installed: 05/02/1988		Rope Size:		
Volts: 480		Complied: 06/12/1995		Entrances: 1		
OWNER		-	OCCUPANT			
CAPITAL BANK		CAPITAL BANK				
333 FAYETTEVILLE STREET		445 S MAIN				
RALEIGH, NC, 27601		BURLINGTON, NC, 27215				
		IN	SPECTION INFORMATION			
Inspection Date 11/22/2017		Type Inspection Routine	Certificate Status Re-issued	Inspector 73 - James	County ALAMANCE	
			VIOLATIONS			
	Provide a class ABC fit Replace jack packing	re extinguisher in the machiner	y space.Current one has expired in	spection		
	be corrected by: 01/21					
complainace w	ith current codes.		when the following corrections have	e been made in order to bri	ng your equipment into	
Violations poin	ted out to: Ashley Fost	er 336 506 1687		Inspector		

CAPITAL BANK

333 FAYETTEVILLE STREET RALEIGH, NC, 27601

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to: