



N C Department of Labor Elevator Bureau  
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in  
any correspondence relating to your equipment  
[www.nclabor.com/elevator.htm](http://www.nclabor.com/elevator.htm)  
919-707-7927

Report Number  
**17331-73-3482**  
State Number  
**H2829**

EQUIPMENT INSPECTED

State Number: <b>H2829</b>	Type of Unit: Hand Lift	Floor to Floor: 1 to 2
Capacity: 750	Manuf: SAVARIA	Speed: 8
Landings: 2	Installed: 12/21/2016	Rope Size:
Volts: 120	Complied:	Entrances: 2
OWNER	OCCUPANT	
CROSS LINKS COMMUNITY CHURCH	CROSS LINKS CHURCH	
1030 MEBANE OAKS ROAD	3445 OLD HILLSBORO ROAD	
MEBANE, NC, 27302	MEBANE, NC, 27302	

INSPECTION INFORMATION

Inspection Date 11/27/2017	Type Inspection Routine	Certificate Status Re-issued	Inspector 73 - James	County ALAMANCE
-------------------------------	----------------------------	---------------------------------	-------------------------	--------------------

1

VIOLATIONS

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: kitty keece 9193040600

Inspector \_\_\_\_\_

THIS IS NOT AN  
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

CROSS LINKS COMMUNITY CHURCH  
1030 MEBANE OAKS ROAD  
MEBANE, NC, 27302