

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 17335-48-1169 State Number 16529

9

		EQUIP	MENT INSPECTED		
State Number: 16529 Capacity: 650 Landings: 4 Volts: 440 OWNER SMITHFIELD HOG PRODUCTION BLADENSBORO, NC, 28320		Type of Unit: Specia Manuf: SIDNEY Installed: 04/28/199' Complied: 04/30/199	7		
		INSPECT	TION INFORMATION		
Inspection Date Type Inspection			Certificate Status	Inspector	County
12/01/2017		Routine	Re-issued	48 - Martin	BLADEN
		,	VIOLATIONS		
2.15.2.2 N/A 2.20.6.8	CORRECT	worn / damaged car guide means. LEVELING ON TOP FL. [LEVELING H st ropes. [CWT. HITTING SPRING BUFF	_		
Elevator Na					
Notify the Elevato complainace with		ting on Corrected Violations Form when t	he following corrections have b	been made in order to bring yo	ur equipment into
Violations pointed out to: ALLAN				Inspector	
THIS IS N INVO		To make changes to the invoice mailing a An invoice will be mailed to:		72 CTION	