N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
17335-76-0731
State Number
H1558

EQUIPMENT INSPECTED

State Number: **H1558**	Type of Unit: Hand Lift	Floor to Floor: 1 to 3
Capacity: 750	Manuf: NATL W-O-V	Speed: 20
Landings: 3	Installed: 12/14/2004	Rope Size: 0
Volts: 115	Complied: 01/04/2005	Entrances: 3

OWNER	OCCUPANT
FIRST BAPTIST CHURCH	FIRST BAPTIST CHURCH
PO BOX 370	220 EAST CROSSNORE DRIVE
CROSSNORE, NC, 28616	CROSSNORE, NC, 28616

INSPECTION INFORMATION

Inspection Date	Type Inspection	Certificate Status	Inspector	County
12/01/2017	Routine	Re-issued	76 - Crank	AVERY

6

VIOLATIONS

2.14.7.1.3 Place the in-car emergency lights in working order. The auxillary lighting illumination shall not be less than 2 lx (0.2 fc) measured at any point between 48 in. and 35 in. above the car floor and approximately 12 in. centered horizontally in front o

8.6.4.8.2 Articles or materials not necessary for the mainternace or operation of the elevator shall not be stored on the elevator

2.27.1.1.1 Place the in-car Emergency Phone in working order.

Items must be corrected by: 01/30/2018

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into complainace with current codes.

Violations pointed out to: First baptist church 828-733-5243 Inspector _____

THIS IS NOT AN INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to: FIRST BAPTIST CHURCH
PO BOX 370
CROSSNORE, NC, 28616