



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
17335-76-3179
State Number
25534

EQUIPMENT INSPECTED

State Number: 25534	Type of Unit: Dumbwaiter	Floor to Floor: 1 to 2
Capacity: 500	Manuf: ATLAS	Speed: 50
Landings: 2	Installed: 01/17/2012	Rope Size: 1/4
Volts: 208	Complied:	Entrances: 1
OWNER	OCCUPANT	
CROSSNORE SCHOOL	MARY IRWIN BELK DINING HALL	
100 DAR DRIVE	220 HORTON STREET	
CROSSNORE, NC, 28616	CROSSNORE, NC, 28616	

INSPECTION INFORMATION

Inspection Date 12/01/2017	Type Inspection Routine	Certificate Status Re-issued	Inspector 76 - Crank	County AVERY
-------------------------------	----------------------------	---------------------------------	-------------------------	-----------------

6

VIOLATIONS

- 2.7.3.1 Provide clear access to the elevator
- 2.2.5.1 Place the freight cab interior lights in working order. 25 lx or 2.5 fc @ the cab floor.
- 8.6.10.2 Keys required for access, operation, inspection, maintenance, repair, and emergency access shall be made available only to qualified elevator personnel.

Items must be corrected by: 03/01/2018

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Don Holbrook 828-733-5031

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:
CROSSNORE SCHOOL
100 DAR DRIVE
CROSSNORE, NC, 28616